



AMD Windows Catalyst Driver  
Release Notes

---

**Table of Contents**

1. Overview .....	2
2. New in this Release .....	2
3. OS & Processor Family support.....	2
4. Supported feature list .....	3
5. Processor Display support.....	4
6. Platform configurations .....	4
7. SW Package .....	6
8. SW Package - Graphics Driver Version.....	7
9. Notes on Validation .....	11
10. Support.....	11

## 1. Overview

Windows Embedded Catalyst Drivers include a set of drivers to enable Graphics and peripheral devices on selected development platforms.

## 2. New in this Release

- Catalyst & Chipset drivers refresh for Embedded R2000, V2000

<b>Catalyst/Graphics Driver Support.</b> <b>Win11, x64 bit</b> <b>Win10, x64 bit</b>	Radeon Software Version	25.4.1
	AMDVER	31.0.21923.1000
	Driver Packaging Version	250306a-415645C
<b>Chipset Driver</b>	AMD_Software_7.06.04.450	

## 3. OS & Processor Family support

Processor family	AMD Program	Win11 24H2 x64 bit	Win10 X64 bit
R2000 Series	Picasso FP5	Yes	Yes
V2000 Series	Renoir FP6	Yes	Yes

#### 4. Supported feature list.

Features Group	Features category	V2000 Series	R2000 Series
3D	OGL 4.6	Yes	Yes
3D	Vulkan	Yes	Yes
Display	4K Cinema	Yes	Yes
Display	Number of displays	Refer display support table below	
Display	DP MST	Yes	Yes
Multimedia	H.264 decode	Yes	Yes
Multimedia	H.265 decode	Yes	Yes
Multimedia	VP9 decode	Yes	Yes
Multimedia	10-bit decode	Yes	Yes
Audio	DP Audio	Yes	Yes
External discrete graphics card (dGPU) validation	Refer table for dGPU pairing	No	No
Eyefinity	Auto Eyefinity (MST)	Yes	Yes
Eyefinity	Mixed rotation	No	Yes
Eyefinity	Mixed Alignment	Yes	Yes
Eyefinity	Tiled display SLS(4x1,3x1,2x1etc..)	Yes	Yes
Eyefinity	Mixed Tiled display (2x2 ,1x3 etc...)	Yes	Yes
Eyefinity	Tiled Groups (1x2+1 ,1x2 + 1x2 etc...)	Yes	Yes
Eyefinity	Multi GPU (Eyefinity on single GPU)	No	No
Eyefinity	Bezel Compensation	Yes	Yes
EDID management	Advance Feature	Yes	Yes
Custom timing	Advance Feature	No	No
10-bit color	Advance Feature	Yes	No
dGMA	OpenGL	No	No
dGMA	OpenCL	No	No
OpenGL	OpenGL	Yes	Yes
OpenCL	OpenCL	Yes	Yes
Peripherals	AHCI Drivers	Yes	Yes
Peripherals	AMD PSP Drivers	Yes	Yes
Peripherals	USB 3.0 Driver (ITB)	Yes	Yes
Peripherals	eMMC driver (ITB) (HS400 mode only)	No	Yes

Peripherals	Ethernet driver	No	No
Peripherals	Audio driver	Yes	Yes
Peripherals	GPIO2	Yes	Yes
Peripherals	I2C	Yes	Yes
Peripherals	UART	Yes	Yes
Peripherals	SMBUS	Yes	Yes
Peripherals	Watchdog	Yes	Yes
Peripherals	SPI	Yes	Yes
Peripherals	Serial (UART w/ COM interface)	Yes	Yes

## 5. Processor Display support

APUs	Max No of display
R2000 Series <ul style="list-style-type: none"> <li>• R2544</li> <li>• R2514 &amp; R2314</li> <li>• R2312</li> </ul>	<ul style="list-style-type: none"> <li>• 4x 4K60</li> <li>• 4x 1080p60 / 3x 4K60</li> <li>• 3x 4K60</li> </ul>
V2000 Series <ul style="list-style-type: none"> <li>• V2516 &amp; V2546</li> <li>• V2718 &amp; V2748</li> </ul>	<ul style="list-style-type: none"> <li>• 4x 4K60 / 4x 4K30</li> </ul>

## 6. Platform configurations

- a) R2000 Platform (Bilby)

<b>R2000 Platform (Bilby)</b>	
Processor family	R2000 Series
Model (CPU config, CPU Base Frequency, GPU config, nominal TDP)	<b>R2312</b> (2C/4T, 2.7 GHz CPU, 3 Vega CUs, 15W) <b>R2314</b> (4C/4T, 2.1 GHz CPU, 6 Vega CUs, 15W) <b>R2514</b> (4C/8T, 2.1 GHz CPU, 8 Vega CUs, 15W) <b>R2544</b> (4C/8T, 3.35 GHz CPU, 8 Vega CUs, 45W)
BIOS version	RBP1004A
VRAM setting	<b>R2312 &amp; R2314</b> : 4GB <b>R2514 &amp; R2544</b> : 8GB
RAM (DDR4)	<b>R2312</b> : 2x8GB 2400 MT/s Non-ECC <b>R2314</b> : 2x8GB 2667 MT/s Non-ECC <b>R2514</b> : 2x16GB 2667 MT/s ECC <b>R2544</b> : 2x16GB 3200 MT/s ECC
Display Convertors / Dongles Used	DP Direct Cable, HDMI Direct Cable, DP-HDMI converter
Storage disk	M.2 SATA SSD, eMMC

## b) V2000 Platform (Celadon)

<b>V2000 Platform (Celadon)</b>	
Processor family	V2000 Series
Model (CPU config, CPU Base Frequency, GPU config, nominal TDP)	<b>V2516</b> (6C/12T 2.1GHz CPU, 6CUs GPU, 15W) <b>V2546</b> (6C/12T 3.0GHz CPU, 6CUs GPU, 45W) <b>V2718</b> (8C/16T 1.7GHz CPU, 7CUs GPU, 15W) <b>V2748</b> (8C/16T 2.9GHz CPU, 7CUs GPU, 45W)
BIOS version	RCO1008A
VRAM setting	8GB
RAM (DDR4)	2x8GB SODIMM 2667 MT/s (Celadon socketed) 2x16GB SODIMM 3200 MT/s (Celadon DM Non-Nova)
Display Convertors / Dongles Used	DP Direct Cable, HDMI Direct Cable, DP-HDMI converter, Type C- DP, Type C -HDMI, Type C Direct Cable
Storage disk	M.2 NVME

## 7. SW Package

SW Component	WHQL certified drivers	Catalyst Installer Package	Chipset Installer Package	Comments
Display	Yes	Yes	No	Includes Graphics Drivers
PSP	Yes	No	Yes	
SBDrv:acpi	Yes	No	Yes	
SBDrv:SFH	Yes	No	Yes	Not supported on V1000, R1000, V2000, R2000
SBDrv:SFHI2C	Yes	No	Yes	
SBDrv:I2C	Yes	No	Yes	
SBDrv:SMBus	Yes	No	Yes	Null driver (AMD SMBUS Driver)
SBDrv:UART	Yes	No	Yes	Max 4M baud-rates
Audio:ACPBus	Yes	Yes	No	
Audio:HDMI	Yes	Yes	No	
Audio:HDABus	Yes	No	No	I2S & I2STDM not applicable on V2000. I2STDM not applicable to R2000.
Audio:I2S	Yes	Yes	No	
Audio:I2STDM	Yes	Yes	No	
XGBE	Yes	No	Yes	Not applicable for V2000 and R2000.
Ryzen Power Plan	Yes	No	Yes	For V2000, “ <b>AMD Processor Power Management Support</b> ” gets installed as provisional package.
IOV	Yes	No	Yes	Null driver
SMBUS	Yes	No	Yes	<b>Functional driver</b> (AMD Emb SMBUS Driver) Block R/W Ops has data mismatch error on first byte.
CIR	Yes	No	Yes	<b>Null driver</b> (Feature not supported on V1000, R1000, R2000, V2000)
USB 3.1	Yes	No	Yes	
GPIO2	Yes	No	Yes	
Serial	Yes	No	Yes	<b>Drivers: UART with COM interface. Max Baud rate: 115200, 3M, 4M bauds</b>
Watchdog	Yes	No	Yes	

## 8. SW Package - Graphics Driver Version

The graphics driver package is also termed as 'ESE 25Q2 Driver' or 'Radeon Software'.

This package contains various independent drivers. Below are the version numbers of Radeon software and other drivers included. The same should also be visible with Radeon Software->System->Software & Driver Details.

S. No	SW Driver Description	Version
1	Radeon Software Version	23.19.23.01
2	Radeon Software Edition	Adrenalin
3	AMDVER	31.0.21923.1000
4	Driver Packaging Version	23.19.23.01-250306a-415645C
5	2D Driver Version	8.1.1.1634
6	Direct3D®	12.1
7	OpenGL®	4.6
8	AMD Audio Driver	10.0.1.30
9	Vulkan™ Driver	2.0.279
10	Vulkan™ API	1.3.260

## 10. Known Issues/Limitations

### a. R2000 Platform (Bilby)

1. After chipset installation, when "View Installation Summary Log" is fetched, "Failed to Fetch Version" is observed for some devices.
2. AC3 audio playback is not supported with Win11 24H2 OS.
3. "Try Complex Eyefinity Control panel" fails to launch.
4. CPU & GPU Utilization mismatch observed between AMD Radeon Performance UI and Task manager.
5. EDID UI display numbers are not matching with OS display settings page display numbers.
6. EDID Tab is appearing after few seconds in AMD Radeon Settings Page.
7. Display corruption observed while creating Eyefinity.

8. Few testcases failed (45/79) with OCL Conformance test suite.
9. On R2544 OPN, display corruption and system hang observed during video playback with M& Tv application.
10. On Win11, Core-Isolation/Memory-Integrity feature/HVCI is not enabled by default.

**Workaround:**

- i. In BIOS, Enable IOMMU & SVM
    1. AMD PBS ->NB Configuration->IOMMU->Enable.
    2. Advanced->SVM support->Enabled.
  - ii. In OS, Enable Memory-Integrity in Windows-security or with regkey.
    1. Core Isolation->Memory Integrity->On
    2. With reg key:  
HKLM\SYSTEM\CurrentControlSet\Control\DeviceGuard\Scenario  
s\HypervisorEnforcedCodeIntegrity -> Enabled=1
11. Stutters observed during video playback with EDID emulated.
  12. UMA Buffer size (VRAM) is not reflecting correctly at the OS level after we tried to modify TDPs in the BIOS.
  13. TDR Observed during Unigine Heaven OGL overnight stress
  14. Stutters observed while playing 4K to 1080p transcoded video samples.
  15. Sporadically MPEG, H.264 playback stutter observed after switching from windowed mode to full screen and vice-versa.
  16. Observed overlapping issue on maximizing Tiny renderers Vulkan samples. Issue not seen with DirectX samples.
  17. Stutter observed when video played with MSFT Edge Browser.
  18. Audio & Video Lag observed in Teams/Zoom call with PPT slide show and Edge browser launched individually in 3x4K setup.
  19. Stutter observed on Movies &TV full screen video playback while moving mouse pointer to bring up the seek bar.
  20. EDID UI closes automatically while emulating from secondary display. Primary display can be used.
  21. Orientation tab is grayed out in Display settings with Eyefinity enabled
  22. Sporadically (4/10 times) Green color display observed while performing reboot function with HDMI display (Pixel Format: YCbCr 4:2:0), with LG27UK650 panel.
  23. Sporadically (2/5 times) green display observed with 2x1/1X2 Eyefinity arrangement during restart cycles with HDMI.
  24. Depth Bounds Test Dx11 application crashes while launching.
  25. SD Card hot plug is not detected.
  26. Secondary monitors light up even with MST option turned OFF in monitors (Daisy chain mode).
  27. Stutters & Video Lags observed for all Media formats.

28. Stutters observed for playback through edge browser with multiple monitors connected.
29. Glitches observed in Audio on Zoom calls with multi-monitors connected.
30. Sporadically observing “can't play error 0x800706ba” on Movies and TV App with VP9 video after resuming from sleep.
31. Sporadically resolution mismatch observed after creating Eyefinity using “Quick Setup”.
32. Video hang and TDR observed when forward and rewind the H265 video.
33. Position Windows Taskbar functionality not working in Radeon Additional settings.
34. Display light up fails on 2nd and 3rd DP display with LG monitor after reboot.
35. 2x2 Eyefinity is not working with FIT and Expand layout.
36. USBC display light up issues observed on onboard USBC display port 0
37. Stutters observed during HEVC Video playback with USBC display connected to onboard USBC port.
38. Platform is getting powered "ON" using (USBC) Type-C to Type-C display without using a power adapter.
39. With USBC display connected to onboard USBC port, errors are observed in log files during long run S3 cycles like ‘system rebooted unexpectedly, ACPI errors and device instance errors’.
40. CPU Utilization mismatch observed between AMD Radeon Performance UI and Task manager.
41. Sporadically TDR observed while resuming from S3 with EDID emulated displays
42. 3x1 Eyefinity creation fails after enabling and disabling 2X1 Eyefinity.
43. EDID UI display numbers are not matching with OS display settings page display numbers.
44. GFX option under Die 0 is missing from Thermal Checker in AMD AVT
45. Observed AMDRadeonSettings Installation UI Crash during driver only Installation.
46. I2STDM driver supports both I2S & I2STDM functionality.  
For I2S functionality, use below workaround.  
**Workaround:** Uninstall ACPBus & I2STDM drivers obtained by default from Catalyst driver. Install explicitly provided ACPBus and I2STDM drivers after reboot.

#### R2544/R2514 Only

47. System hang observed after resume from S3 on few systems 3 out of 5 times

#### b. V2000 Platform (Celadon)

1. After chipset installation, when "View Installation Summary Log" is fetched, "Failed to Fetch Version" is observed for some devices.

2. AC3 audio playback is not supported with Win11 24H2 OS.
3. "Try Complex Eyefinity Control panel" fails to launch.
4. SPI RDID Command result shows all 0s.
5. Failed Creating the Direct3D device error observed while launching Barycentrics11 and CrossfireAPI11.
6. Stutters observed while playing 30fps video playback.
7. Chipset Installation is showing successful but log file shows as " FAIL" for AMD Processor Power Management Support.
8. Sporadically (1/5) Multiple display blanks out observed post Eyefinity arrangement [Nx1 or 1XN]
9. Few testcases failed (45/79) with OCL Conformance test suite.
10. Performance drops in Passmark 10(2D Graphics Mark) and Passmark rating on Win11 OS compared to Win10. Disabling VBS & HVC improves performance.
11. Time Based Profiling and Power Profiling in AMDuProf tool is not supported in Win11 22H2 OS.
12. Modern Standby is not supported on RS5 with SATA SSD.  
**Workaround:** Use NVMe M.2 disk
13. BIOS settings to enable S3 (default settings):
  - i. AMD PBS ->S3/Modern Standby S3 enable.
  - ii. Boot UEFI OS Fast Boot Option --> Disable.
14. BIOS settings required for Modern Standby:
  - iii. AMD PBS -> S3/Modern Standby Support = <Modern Standby Enable>
  - iv. AMD PBS -> Modern Standby Type = <Modern Standby + S0i3>
  - v. AMD PBS -> Reduced Hardware Support = <Enabled>
15. BIOS Settings to avoid yellow bang with I2C and UART enabled in BIOS:
  - vi. Setup Utility->AMD PBS->NFC Support->Disabled
  - vii. Setup Utility->AMD PBS->ALS Support->Disabled
  - viii. Setup Utility->AMD PBS->Touch Panel Support->Disabled
  - ix. Setup Utility->AMD PBS->Touch Pad Support->Disabled
16. S3 is enabled by default in BIOS. If switched to MSB, re-install graphics and chipset drivers.
17. Display or media player blank out observed only once for few seconds, on playing video after shutdown & boot. If media player is not recovering, re-open the media player.
18. Setup failed Error during hot unplug after quick Eyefinity.
19. Tearing with Eyefinity: All displays will be tear free only if all displays are using the same timing and same connector type
20. Display blank out is observed for Eyefinity in portrait mode.
21. Sporadically Display blank out, system hang, BSOD is observed during video playback with Eyefinity arrangement.
22. Eyefinity is not functional with mix of DP and HDMI monitors.

23. Using Quick Setup Vertical position Eyefinity configuration fails for 1st time.
24. Sporadically observing system hung during reboot with 2x1 or 1x2 Eyefinity configuration.
25. BSOD observed while doing AMDDeSPI tool command execution.
26. EDID UI display numbers are not matching with OS display settings page display numbers.
27. Eyefinity creation failing after trying N-1X1 or 1XN-1 Eyefinity with N displays connected.
28. Vulkan GLTF samples are crashed followed by hang while doing resize to minimum.
29. Observed AMDRadeonSettings Installation UI Crash during driver only Installation.
30. Sporadically (1/5) system not entering MSB because of active High-definition audio controller.

#### d. Eyefinity (V2000, R2000)

31. Very Sporadically TDR observed during Eyefinity creation
32. TDR and system hang observed during S3 long run.
33. Setup failed Error during hot unplug after quick Eyefinity.
34. Tearing with Eyefinity: All displays will be tear free only if all displays are using the same timing and same connector type.
35. Display blank out is observed for Eyefinity in portrait mode.
36. Sporadically Display blank out, system hang, BSOD is observed during video playback with Eyefinity arrangement.
37. Eyefinity is not functional with mix of DP and HDMI monitors.
38. Using Quick Setup Vertical position Eyefinity configuration fails for 1st time.
39. Sporadically observing system hung during reboot with 2x1 or 1x2 Eyefinity configuration.

## 9. Notes on Validation

1. R2000 and V2000 are validated with Win11 24H2 OS version.
2. R1000, V1000 and Windows-10 OS version are NOT validated with these drivers.

## 10. Support

Please contact your Field Application Engineer for support on this release.

© 2025 Advanced Micro Devices, Inc. All rights reserved.

The information contained herein is for informational purposes only and is subject to change without notice. While every precaution has been taken in the preparation of this document, it may contain technical inaccuracies, omissions and typographical errors, and AMD is under no obligation to update or otherwise correct this information. Advanced Micro Devices, Inc. makes no representations or warranties with respect to the accuracy or completeness of the contents of this document, and assumes no liability of any kind, including the implied warranties of noninfringement, merchantability or fitness for particular purposes, with respect to the operation or use of AMD hardware, software or other products described herein. No license, including implied or arising by estoppel, to any intellectual property rights is granted by this document. Terms and limitations applicable to the purchase or use of AMD's products are as set forth in a signed agreement between the parties or in AMD's Standard Terms and Conditions of Sale. Any unauthorized copying, alteration, distribution, transmission, performance, display or other use of this material is prohibited.

### Trademarks

AMD, the AMD Arrow logo, AMD AllDay, AMD Virtualization, AMD-V, PowerPlay, Vari-Bright, and combinations thereof are trademarks of Advanced Micro Devices, Inc. Other product names used in this publication are for identification purposes only and may be trademarks of their respective companies.

Dolby is a trademark of Dolby Laboratories.

HDMI is a trademark of HDMI Licensing, LLC.

HyperTransport is a licensed trademark of the HyperTransport Technology Consortium.

Microsoft, Windows, Windows Vista, and DirectX are registered trademarks of Microsoft Corporation in the US and/or other countries.

MMX is a trademark of Intel Corporation.

OpenCL is a trademark of Apple Inc. used by permission by Khronos.

PCIe is a registered trademark of PCI-Special Interest Group (PCI-SIG).

USB Type-C® and USB-C® are registered trademarks of USB Implementers Forum.

Reverse engineering or disassembly is prohibited.

USE OF THIS PRODUCT IN ANY MANNER THAT COMPLIES WITH THE MPEG ACTUAL OR DE FACTO VIDEO AND/OR AUDIO STANDARDS IS EXPRESSLY PROHIBITED WITHOUT ALL NECESSARY LICENSES UNDER APPLICABLE PATENTS. SUCH LICENSES MAY BE ACQUIRED FROM VARIOUS THIRD PARTIES INCLUDING, BUT NOT LIMITED TO, IN THE MPEG PATENT PORTFOLIO, WHICH LICENSE IS AVAILABLE FROM MPEG LA, L.L.C., 6312 S. FIDDLERS GREEN CIRCLE, SUITE 400E, GREENWOOD VILLAGE, COLORADO 80111.